

## **STATEMENT**

## tesa® 60630, 60632, 60650, 60652, 60670, 60672

A.m. tesa products were tested at an UL facility in accordance with the requirements in UL 510A (Standard for Component Tapes – Edition 1 – Issue date 2017/05/03).

Flammability of the tapes was evaluated according to Clause 20 - Flame Test.

Compliance Criteria: No single flame application shall exceed 60 seconds; the tape shall not emit particles that ignite the cotton; damage (burning or charring) to indicator flag shall not exceed 25% (soot that can be wiped away with cloth or fingers and brown scorching is not considered damage)

| tesa tape  | Maximum Flame Duration after removal of burner, seconds | Ignition of Cotton | Comply with test<br>Critera |
|------------|---|--------------------|-----------------------------|
| tesa 60630 | 12  | No                 | Yes                         |
| tesa 60632 | 26  | No                 | Yes                         |
| tesa 60650 | 7   | No                 | Yes                         |
| tesa 60652 | 4   | No                 | Yes                         |
| tesa 60670 | 3   | No                 | Yes                         |
| tesa 60672 | 4   | No                 | Yes                         |

Dr. Anja Köth

Product Safety Department Phone: +49 40 888993938 Email: Anja.koeth@tesa.com



A Beiersdorf Company October 29, 2018